

## Width Measurement at the Slab Reheat Furnace

### Problem:

Incorrect slab placed into reheat furnace could cause incorrect product to customer due to a scheduling mix-up

### Solution :


Accurately measure the width prior to the furnace charging position

### Equipment:

- Two LM-500-LR7, Triangulation Laser Meters

### Features:

- Non-contact
- Accuracy to 0.76mm
- Safety
- Easy installation and maintenance



### Locations:

On the feed tables at the rear of slab reheat furnaces