

Thin Slab Radius Measurement

Problem:

Excessive movement of strand radius is a contributing cause to breakouts in thin slab casters.

Solution:


Using a microwave sensor to accurately measure the radius of the stand will enable the radius to be maintained within the correct tolerance dimensions.

Equipment:

- MWS-3000-K10

Features:

- Non-contact
- Accuracy 1 to 5mm (dependant on range)
- Range 0.5 to 80 meters
- Safety
- Easy installation and maintenance



Locations:

Thin Slab Casters