

# Width Measurement at the Slab Reheat Furnace

## Problem:

Incorrect slab placed into reheat furnace could cause incorrect product to customer due to a scheduling mix-up

## Solution :


Accurately measure the width prior to the furnace charging position

## Equipment:

- Two LM-500-LR7, Triangulation Laser Meters

## Features:

- Non-contact
- Accuracy to 0.76mm
- Safety
- Easy installation and maintenance



## Locations:

On the feed tables at the rear of slab reheat furnaces